

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
WASH.
29-ANAC,
I-I-

Curtis Wharf, Creamery
"O" and Second Streets
Anacortes
Skagit County
Washington

HABS No. WA-198-I

John Stamets, Photographer, WA-198-I-1 through WA-198-I-5,
June of 1992.

- WA-198-I-1 Creamery, north facade.
- WA-198-I-2 Creamery, east facade, north section.
- WA-198-I-3 Creamery, east facade, south section.
- WA-198-I-4 Creamery, interior of north section, looking
 into the southwest corner.
- WA-198-I-5 Creamery, interior of south section, view
 looking north. Sawdust is from the insulated
 walls. The ceiling, with the condenser coils,
 has collapsed.
- WA-198-I-6 Photocopy of photograph (Original print, Phillip
 McCracken; courtesy of Bill Mitchell.) Photo-
 grapher unknown, 1922. Creamery, east facade,
 north section.

Note: For additional written historical and descriptive
information, please see the main entry for the Curtis Wharf,
HABS No. WA-198.